

Proposal 15535
Salt Dome Roof Restorations for 8 Maintenance Garage Locations in
Iowa
Questions and Responses Set 2

Q1) Several of the salt dome shingle areas have been color coded. Is there a reason for this?

R1) No, there is not a reason for the different color shown on some drawings for the shingles. The CAD drafter assigned a color for those drawings so they could see it better on the screen and it did not get changed to black line for the final drawings.

Q2) Are the poured concrete walls still supposed to be a part of the new foam application?

R2) The poured concrete walls are to be covered with the over coating material and does not need to be covered with the foam. See Addendum No. 2, Section 07 5700 with revision date 12-21-2012, Paragraph 3.05.D.

Q3) The Desoto dome in Adel currently has foam and coating on it already. Is this dome supposed to get more foam and coating or should this one just be a new coating application?

R3) The Desoto Dome has a Urethane foam coated roofing system that was damaged by hail and is leaking. The contractor will apply the new coated roofing system over the existing coating system.