

Iowa Department of Transportation

Office of Motor Carrier Services



5
Audubon

The following are roads that cannot be traveled on:

Between sections 15 and 22, T79N-R35W due to high truss bridge.