

Table N

Price Adjustment for PCC Pavement Edge Damage

Price Adjustment Per Lineal Foot of Damage			
Damage up to 2 inches in depth or width	Damage greater than 2 inches and up to 4 inches in depth or width	Damage greater than 4 inches and up to 6 inches in depth or width	Damage greater than 6 inches in depth or width
\$2.50	\$5.00	\$12.50 *	Patch and \$12.50

1. Length used to calculate price adjustment will be determined based upon the length of the panel damaged.

Example - A 20 foot panel has 4 feet of damaged edge. The length of price adjustment will be 20 lineal feet.

2. Price adjustment for edge damage at a transverse joint that falls within both adjacent panels will be calculated based upon the length of both panels.

Example - Edge damage occurs at a transverse joint location in a PCC overlay with 5 foot panel lengths. Length of price adjustment will be 10 feet.

3. Price adjustment level for a panel will be based upon the most severe damage in the panel.

Example - Most of the damage within a panel is less than 2 inches in width, but some is between 2 and 4 inches wide. The full panel length will be price adjusted \$5.00 per lineal foot.

4. For damage greater than 6 inches in width or depth, full or partial depth repair will be required in addition to a price adjustment of \$12.50 per lineal foot of damage as calculated above.

* The Engineer may elect to require partial depth repair (for full depth pavements or thick overlays) or full depth repair (for thin overlays) instead of price adjustment.

Note: Contact the Construction Office for recommended repair procedures when patching is required.

