



NOTE: BRACKET SHALL PROVIDE FOR COMPLETELY CONCEALED WIRING OF SIGNAL HEADS.

REV.	DATE	BY	MAST ARM SIGNAL BRACKET	FIGURE: 8010.8
DATE: 04-04-97				SHEET 1 OF 1