

**Proposal 15535**  
**Salt Dome Roof Restoration for Eight Various Locations in Iowa**  
**Department of Transportation Hanlontown, Desoto, Sidney, West**  
**Burlington, Tipton, Anamosa, Marion and Davenport**  
**Questions and Responses Set 1**

**Q1) Are you wanting vents raised?**

**R1 No, if we have one that needs raised we choose to encapsulate it so water or moisture does not get in. (See Specification Section 07 5700- Revised 12-21-2015, Paragraph 3.03.D).**

**Q2) What are you talking about when you say carpentry?**

**R2) Inside and entrance area may have carpentry work and there is a \$5,000.00 allowance per dome location (See Specification Section 01 2100, Paragraph 1.05.A).**

**Q3) Do you want a base coat and top coat?**

**R3) Yes (See Specification Section 07 5700- Revised 12-21-2015, Paragraph 3.05.A).**

**Q4) The warranty length of 20 years? On the previous projects the warranty period was 10 years. Just wondering where the 20 years came from?**

**R4) Warranty has been changed to 10 years to match the drawings in Specification Section 07 5700- Revised 12-21-2015, Paragraph 1.07).**

**Q5) The second is the thickness of the spec. In one area it calls for the Permathane II spec which is 36 mils and in another is calls for 20 mils in 2 passes. Just wondering about that change as well?**

**R5) In Specification Section 07 5700 (Revised 12-21-2015), Paragraph 3.05.C to read as follows: Apply overcoat in a two or three coat urethane coating system as required by manufacturer to a total dry film thickness of 36 mils minimum.**

**Clarification: it must be 50 degrees and above to do the needed roof restoration. The color is to be White. This is already included in Section 07 5700 (Revised 12-21-2015), Paragraphs 1.06 and 2.03.**