

Proposal 15563

Ames Complex Restroom Remodel at Repair shop. Questions and Responses Set 1

Q1) In the Spec book on 01 4000-1 there is a reference for an allowance that refers to sheet 01 2100 but there is no 01 2100 in the specs. As with that in the Spec book for RFB 15581 on 03 300-5, 3.09 A says Iowa DOT will perform quality control tests. Is this referring to concrete testing? Is this testing for both RFB's or just 15581?

**R1) Allowance Section has been added to the Specification, section 01 2100 Quality control tests for concrete will be performed by a testing agency coordinated by the contractor.
Section 03 3000 has been revised to read as such.**

Q2) RFB 15563 What are the wall types for this RFB?

R2) Added Sheet A-0 to bid documents

Q3) RFB 15563 On Plan page A-2 it appears that there are new spaces on the south and east walls of the Men's restroom, are these new stud framed walls? Also on the south wall of the women's restroom where the new grab bar goes it shows a new stub wall being built out for the grab bar to be attached to. Is this going to be steel stud and gypsum or a block wall?

R3) See sheet A-0

Q4) RFB 15563 On the west wall of the men's restroom on sheet A-2 there appears to be a cabinet that is the same as the one labeled 10F (Tall Cabinet), is this the same type of cabinet?

I've seen reference in the spec books to in-floor heat. Is there any in-floor heat in either RFB's.

R4) There are 2) cabinets both labeled 10F

Q5) I've seen reference in the spec books to in-floor heat. Is there any in-floor heat in either RFB's.

R5) There is no infloor heat in the building and we couldn't find the reference you are referring to. If you could clarify where in the spec we can get that fixed.